SCHEDA TECNICA

Filtro di ricambio Jetstream® per Particolati e Gas Organici A2PSL

Filtro polvere e gas organici A2 PSL per Jetstream® / CBU620-000-000



DESCRIZIONE

Filtro di ricambio A2PSL per unità Jetstream®.

Il filtro Jetstream® A2PSL soddisfa i requisiti della norma EN 12941 se montato sul respiratore Jetstream®.

OPZIONI

Filtro polvere e gas organici A2 PSL per Jetstream® (CBU620-000-000)

STANDARD DI SICUREZZA

EN 12941

JSP Limited. Worsham Mill. Minster Lovell. Oxford OX29 0TA. England.

Tel: +44 (0)1993 826050 / Fax: +44 (0)1993 824411 / Email: sales@jspsafety.com / Web: www.jspsafety.com

Do Not Publish without written permission from JSP Limited. Contact copyright@jspsafety.com. Information correct in the United Kingdom at date of issue and may be subject to change. Any third-party machine and automated translations processed by users may have inaccuracies and should not be relied upon.

SPECIFICHE

Classificazione
TH2 A2PSL

Uso
R (Riutilizzabile)

Efficienza Minima di Filtrazione
98%

Fattore di Protezione Nominale
50 Se montato sull'unità JetStream GVX

METAL FREE

Materiale dell'Involucro
Realizzate in ABS.

BSI Kitemark
Sì

È necessario un test di idoneità al viso

Tipo di filtro
Gas Organici, Odori e Particolati Solidi o Liquidi

Strato di Carbone Attivo
Sì

Massima Penetrazione Consentita (TIL)
2% se montato su Jetstream

Fattore di Protezione Assegnato (UK)
20 Se montato sull'unità JetStream GVX

Materiale del Filtro
Tessuto Filtrante Plissettato e Carbone Attivo

Durata in Stock
3 anni

Peso del Prodotto
Filtro TH2 A2P R SL 592g

RANGE

Jetstream®
ACCESSORIES

DOWNLOAD

Immagini Scaricabili (ZIP)
doc-jetstream.pdf (PDF)

JSP Limited. Worsham Mill. Minster Lovell. Oxford OX29 0TA. England.

Tel: +44 (0)1993 826050 / Fax: +44 (0)1993 824411 / Email: sales@jspsafety.com / Web: www.jspsafety.com

Do Not Publish without written permission from JSP Limited. Contact copyright@jspsafety.com. Information correct in the United Kingdom at date of issue and may be subject to change. Any third-party machine and automated translations processed by users may have inaccuracies and should not be relied upon.